Date: 25th January 2013

# Justification: Safety

# (Maintenance)

This document is the property of Network Rail.

It shall not be reproduced in whole or in part, nor disclosed to a third party, without the written permission of the Owner.

© Copyright 2013 Network Rail.

**AUTHORISATION** 

Authorised by:

Private Owner Circular Letter 663 Issue- Ia

Title

Screw coupling failure.

J. Allenden, Professional Head of Plant and T&RS

POCL 663

Issue: I a

Date: 25th January 2013

## **Amendment Record**

Issue	Date	Amendment
1	25/01/13	First issue
1a	25/01/13	First issue ( with typographical correction)
	-	

Date: 25th January 2013

#### 1. INTRODUCTION

POCL 663, Issue 1a, has been produced as a result of NIR 2883 received indicating that some vehicles may be fitted with an incorrectly rated screw coupling. The manufacturers X-Press Spares Ltd & Co. KG Hovesaatstr.6 48432 Rheine-Germany; believe that the screw coupling 850kN has been sold into the UK to many customers as a replacement for the C1-A2-9000275 since 2007.

N.B. Some couplings ordered to drawing CI A2 90000275 56t rating were delivered as a 34.5t coupling.

Vehicles are required to be fitted with the correct coupling rated as per the design when the vehicle passed Engineering Acceptance.

#### 2. INSTRUCTION

Check the source of your supply of screw couplings. If there is any doubt as to their source or; if they have been supplied by the above supplier; then you should carry out an urgent fleet check to ensure that screw couplings fitted are the correctly rated coupling as per the original Engineering Acceptance Certificate.

## Action Required

 Inspect the screw coupling to identify if it is the correct type. The most effective way to do this is to measure the depth of section at the centre of the connecting rod. See figs 1, 2, & 3.


INCORRECT COUPLING	CORRECT COUPLING	
Rating 34.5 tonne	Rating 56 tonne	
Drawing B1-C0-9029821 item 06 to UIC 520 (see Appendices A to C)	Drawing B1-C0-9029821 item 05 or C1-A2-9000275 (see Appendices A to C)	
Connecting Rod size 35 to 42mm (see figure 3)	Connecting Rod size 52 to 55mm (see figure 3)	
Either no stamping marks or as per example photographs shown in Appendix D	May be stamped BR or 122T	

2. Any screw couplings found to be the incorrect type must be renewed as a complete assembly. Note: the incorrect coupling may be of lower grade steel than the correct version therefore if replacement is required then the entire assembly must be replaced.

Network Rail Page 3 of 9

Date: 25th January 2013

3. Record the details of the wagons checked and any couplings renewed



Screw Coupling



Correct 52-55 mm



Incorrect 35-42mm

Figure 2

Network Rail Page 4 of 9

Date: 25th January 2013



Figure 3

Connecting Rod Dimension to Check (Correct version shown)

Please inform the Senior PWRA Engineer of the outcome of your investigations by 1<sup>st</sup> March 2013.

### 3. SCOPE

This instruction applies to all PWRA Owners operating vehicles fitted with UIC screw couplings.

### 4. IMPLEMENTATION

This document shall be implemented immediately.


In the event of any query arising, or clarification required, please contact:


Senior PWRA Engineer Network Certification Body Caldecotte - Ground Floor, The Quadrant MK Elder Gate, Milton Keynes, MK9 1EN

Network Rail Page 5 of 9

Date: 25th January 2013

## Appendix A- extract from drawing B1-C0-9029821







DRAWING NO. CI-AZ-9000275 GPR COUPLING.
CRAWING NO. CI-AZ-9000275 GPR CAI NO. 73.7290
(B.R.DESIGN) SUPERSEDES R.C.H.2827
TRACTION LOAD: 56 t
PROOF LOAD: 71 t

**POCL 663** 

Date: 25th January 2013



Date: 25th January 2013



Appendix D Example photographs of incorrect screw coupling

Date: 25th January 2013











Network Rail Page 9 of 9