Issue: 2

Date: 17 September 2007

Justification: - Instruction

(Safety)

This document is the property of Network Rail.

It shall not be reproduced in whole or in part, nor disclosed to a third party, without the written permission of the Owner.

© Copyright 2007 Network Rail.

**ENDORSEMENT & AUTHORISATION** 

Endorsed by:

Authorised by

D. Minshull, Senior Standards Engineer

K. Stannard, Vehicle Conformance Engineer

Private Owner Circular Letter 618 - Issue 2

Lifting and Handling of Wagons at Maintenance Events

Issue: 2

Date: 17 September 2007

## 1. INTRODUCTION

POCL 618, Issue 2 has been produced to remind Owners that any procedures used to lift or handle wagons at maintenance events should have no detrimental effect upon their subsequent safety in service. This POCL has been re-issued because the initial version only covered "lifting by buffers". POCL 618, Issue 2 makes it clear that any handling or lifting processes used at maintenance events shall neither cause damage nor compromise operational and safety performance.

## 2. INSTRUCTION

It is the Owner's responsibility to ensure that wagons are lifted and handled during maintenance events such that safety in operational service is not compromised.

The Owner shall satisfy himself that all handling and lifting procedures used do not:

- a). Cause damage to the wagon structure or components.
- b). Compromise operational and safety performance.

All procedures for lifting or handling of wagons shall be fully detailed in the Owner's relevant maintenance documentation.

## 3. SCOPE

This POCL is applicable to all PWRA wagons that operate on Network Rail controlled infrastructure.

## 4. IMPLEMENTATION

This document shall be implemented immediately.

In the event of any query arising, or clarification required, please contact:

Senior Standards Engineer PWRA Management Group Room 225 Derwent House rtc Business Park London Road Derby DE24 8UP

Network Rail Page 2 of 2