Issue I

Date: September 2006

Justification: Safety Instruction

(Maintenance)

Private Owner Circular Letter 619 Issue I

Title

Prohibition of Jacking or Lifting Wagons by Centre Couplers

ENDORSEMENT & AUTHORISATION

Dunkrich and

Endorsed by:

D. Minshull, Senior Standards Engineer

Authorised by:

K. Stannard, Vehicle Conformance Engineer

Network Rail Page 1 of 3

Issue I

Date: September 2006

I. INTRODUCTION

As reported by NIR 1840, an iron ore tippler train became divided at Appleby in July 2004, as a consequence of the wagon's underframe failing beneath the centre coupler tail pin.


Investigations have identified that the superstructure of certain centre coupler fitted wagons was not designed to accommodate high vertical loads in the area beneath the tail pin.

This POCL has been issued to prohibit either the Jacking or lifting of such wagons by the centre couplers in order to reduce the likelihood of high loads being exerted in the superstructure beneath the centre tail pin.

2. SCOPE

This instruction is applicable to PWRA registered wagons fitted with centre couplers where the coupler tail pin is retained by a pin retaining plate located in cut-outs in the wagon underframe, as shown by the adjacent photograph.

Cut-outs in underframe Tail pin retaining plate -



3. INSTRUCTION

To reduce the possibility of adverse lifting loads being transmitted into the centre coupler tail pin support plate and adjacent underframe on these wagons, the lifting or jacking of this design of wagon by any means involving the centre coupler is **prohibited**.

Lifting or jacking of wagons via the centre coupler is only permitted in cases where the Owner can demonstrate the wagon design (and specifically tail pin support plate area) has been designed to accommodate lifting loads via the coupler and underframe, and where appropriate lifting controls are implemented.

Network Rail Page 2 of 3

Issue I

Date: September 2006

4. IMPLEMENTATION

This POCL shall be implemented immediately.

In the event of any query arising, or clarification required, please contact:

Senior Standards Engineer PWRA Management Group Room 225 Derwent House rtc Business Park London Road Derby DE24 8UP

Network Rail Page 3 of 3