Issue: 2

Date: May 2005

Justification: Instruction

(Maintenance)

This document is the property of Network Rail.

It shall not be reproduced in whole or in part, nor disclosed to a third party, without the written permission of the Owner.

 $\hfill \hbox{$\odot$}$ Copyright 2005 Network Rail.

Private Owner Circular Letter 331 Issue 2

Title

Greasing of Steelon-Steel Centre Pivots

ENDORSEMENT & AUTHORISATION

Endorsed by:

D. Minshull, Senior Standards Engineer

Authorised by:

K. Stannard, International Vehicle Engineer

Network Rail Page | of 2

Issue: 2

Date: May 2005

I. INTRODUCTION

POCL 331 Issue 2 confirms the grease to use for lubricating centre castings having a steel-to-steel contact.

2. INSTRUCTION

Centre castings having a steel-to-steel contact interface shall be lubricated using a calcium based, graphited grease of number two consistency (BR Cat. No. 27/1361). Greasing shall be carried out whenever the vehicle body is lifted off the bogie and as required by the maintenance plan. (Under no circumstances shall the period between re-greasing exceed eight years). When carrying out greasing ensure that any drain holes are not blocked.

Note: Where non-metallic liners are fitted centre pivots shall not be lubricated.

3. SCOPE

This instruction applies to all PWRA vehicles that operate on Network Rail Controlled Infrastructure.

4. IMPLEMENTATION

This document shall be implemented immediately.

In the event of any query arising, or clarification required, please contact:

Senior Standards Engineer PWRA Management Group Room 225 Derwent House rtc Business Park London Road Derby DE24 8UP

Network Rail Page 2 of 2